

0034



Norman H. Bangerter

Governor

Dee C. Hansen

Executive Director

Dianne R. Nielson, Ph.D.

Division Director

## State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

355 West North Temple

3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203

801-538-5340

## INSPECTION REPORT

INSPECTION DATE & TIME: September 14, 1989  
9:00am - 11:00am

Permittee and/or Operators Name: Genwal Coal Company  
 Business Address: P.O. Box 1201, Huntington, Utah 84528  
 Mine Name: Crandall Canyon Mine Permit Number: ACT/015/032  
 Type of Mining Activity: Underground ☒ Surface ☐ Other ☐  
 County: Emery  
 Company Official (s): Allen Childs  
 State Official(s): Lynn Kunzler  
 Partial: ☒ Complete: ☐ Date of Last Inspection: August 29, 1989  
 Weather Conditions: Clear and cool  
 Acreage: Permitted 164.4 Disturbed 5.75 Regraded 0.5 Seeded 0.5 Bonded 5.75  
 Enforcement Action: None.

## COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( X )	( )	( )	( X )
2. SIGNS AND MARKERS	( )	( )	( )	( )
3. TOPSOIL	( X )	( )	( )	( X )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( X )	( )	( )	( X )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

**INSPECTION REPORT**  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION: Sept. 14, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits. Genwal had recently submitted responses to several permit stipulations that are currently being reviewed by the tech staff. The operator was reminded of additional stipulation deadlines that needed to be met in within the next month regarding permit renewal and U.S. Forest Service concerns.


3. Topsoil. The three topsoil piles were inspected for vegetation cover and signs of erosion. All topsoil piles were stable. Genwal was currently in the process of replacing some of the straw bales that are being used for protection.

11. Contemporaneous Reclamation. Genwal will be reseeding the outslope of the road (within the permit area) and a small area adjacent to the truck turn-around area where revegetation success from past attempts is limited. The inspector clarified for the new operator that only one seed mix is currently approved for all temporary as well as final revegetation efforts.

Copy of this Report:

Mailed to: Brian Smith - OSMRE, Allen Childs, Genwal, PFO

Given to: Joe Helfrich & Sue Linner - DOGM

Inspectors Signature and Number: 

#17 Date: Oct. 2, 89